

TLC Visualization Laboratory Data Guide

Visualizing Method	Functional/Structural Groups Detected	Concentration/Formulation/Specs	Development Techniques and Storage Suggestions	
UV	Aryls, conjugated systems, chromophore-containing molecules	• N/A	• If toluene used to develop, dry with heat gun before visualizing	
Iodine-sand mixture	Alcohols, unsaturated compounds, and general reagents	• 25 g of sand/silica or sand layer (6 mm deep) • 0.5 g of iodine	• Make sure TLC is dry before visualizing • Shake the visualizing chamber charged with sand/silica and iodine to mix evenly before adding TLC plate • Can also shake the chamber with the TLC plate inside so the I ₂ -saturated sand/silica touches the plate and develops more rapidly • Produces brown or dark purple spots	
Phosphomolybdic acid (PMA)	Alcohols and general reagents	• Range of 10-40% solution of PMA in ethanol	• Submerge in solution • TLC plate turns to light green • TLC plate must be heat-dried (ca. 60° C) after PMA application to visualize • TLC plate turns to light yellow and spots of analyzed materials (reactants and products) will turn to dark green spots	
Sulfuric acid vapor/spray	Alcohols, amines, and general reagents	• 1:1 mixture of conc. H ₂ SO ₄ and water	• Heat if necessary • Produces black spots on beige background	
Potassium permanganate solution	Alcohols, aldehydes, amines, sulfides, or unsaturated compounds	• 1.5 g KMnO ₄ • 10 g K ₂ CO ₃ • 1.25 mL 10% aq NaOH • 200 mL water	• Apply gentle heat if necessary • Should circle spots after visualization, as background darkens over time • Produces yellow or light brown spots on pink to purple background	
Cerium-ammonium-molybdate	General reagents	• 0.2 g Ce ₂ (SO ₄) ₃ • 5 g (NH ₄) ₂ MoO ₄ • 100 mL 5% aq H ₂ SO ₄	• Need to heat to visualize blue-black spots	
Anisaldehyde	Nucleophilic groups and general reagents	• 15 g anisaldehyde • 250 mL EtOH • 2.5 to 5 mL conc. H ₂ SO ₄ (add slowly) • (optional) 1 to 2 mL AcOH (good for visualizing terpenes)	• Store solution in the refrigerator • Light and oxidation sensitive • Heating produces a range of colored spots on pink background • Can use different colored spots to distinguish multiple compounds with similar R _f value	
Ninhydrin	Primary and secondary amines, amino sugars, and amino acids	• 5 g ninhydrin • 150 mL EtOH	OR • 0.3 to 1.5 g ninhydrin • 100 mL <i>n</i> -BuOH • 3 mL AcOH	• Produces blue spots • Boc-amines and secondary amines may require heating to visualize
2,4-Dinitrophenylhydrazine (DNPH)	Aldehydes and ketones	• 3 g DNPH • 750 mL 2M HCl	OR • 12 g DNPH • 60 mL conc. H ₂ SO ₄ • 80 mL water • 200 mL EtOH	• Produces yellow to red spots on orange background without heating
Dragendorff Reagent	Amines, phosphines, and basic nitrogen-containing heterocycles	Solution A: • 1.7 g Bi(NO ₃) ₃ • 20 mL AcOH • 80 mL water	Solution B: • 40 g KI • 100 mL water	• Combine two solutions before use • Solution A and Solution B can be stored separately for about 1 week with refrigeration • Produces brown-orange spots without heating
Vanillin	Alcohols, amines, carbonyls, and general reagents	• 15 g vanillin • 250 mL EtOH • 2.5 mL conc. H ₂ SO ₄		• Heating produces colored spots on pink/beige background
Iron(III) chloride solution	Phenols and enolizable products	• 1% (w/w) solution FeCl ₃ in water	OR • 1% (w/v) solution FeCl ₃ in 50% aq MeOH	• Produces colored spots
Cerium(IV) sulfate solution	General reagents	• Saturated solution of Ce(SO ₄) ₂ in 15% aq H ₂ SO ₄		• Need to heat to visualize a range of colored spots
Bromocresol green	Carboxylic acids	• 0.04 g bromocresol green • 100 mL EtOH • Add 0.1 M aq NaOH dropwise until blue color just appears		• Produces yellow spots on a blue background, usually without heating

Aldrich® Chemistry Reagents to Formulate TLC Dips

Reagents	Purity/Grade	Cat. No.
Iodine-sand mixture		
Sand	50-70 mesh particle size	274739
Iodine	ACS reagent, ≥99.8%, solid	207772
Phosphomolybdic acid (PMA) solution		
Phosphomolybdic acid solution	20 wt. % in ethanol	319279
Phosphomolybdic acid solution	Spray reagent, 10% in ethanol	P4869
Phosphomolybdic acid hydrate	ACS reagent	221856
Ethanol	ACS reagent, ≥99.5% (200 proof), absolute	459844
Sulfuric acid vapor/spray		
Sulfuric acid	ACS reagent, 95.0-98.0%	320501
Potassium permanganate solution		
Potassium permanganate	ACS reagent, ≥99.0%	223468
Potassium carbonate	ACS reagent, ≥99.0%	209619
Sodium hydroxide	ACS reagent, ≥97.0%, pellets	221465
Cerium-ammonium-molybdate solution		
Cerium(III) sulfate	97%	307688
Ammonium molybdate	99.98% trace metals basis	277908
Sulfuric acid	ACS reagent, 95.0-98.0%	320501
Anisaldehyde solution		
Anisaldehyde solution		SRA1
<i>p</i> -Anisaldehyde	98%	A88107
Ethanol	ACS reagent, ≥99.5% (200 proof), absolute	459844
Sulfuric acid	ACS reagent, 95.0-98.0%	320501
Acetic acid	ACS reagent, ≥99.7%	320099
Ninhydrin solution		
Ninhydrin	ACS reagent	151173
Ethanol	ACS reagent, ≥99.5% (200 proof), absolute	459844
Ninhydrin	ACS reagent	151173
1-Butanol	ACS reagent, ≥99.4%	360465
Acetic acid	ACS reagent, ≥99.7%	320099

Reagents	Purity/Grade	Cat. No.
2,4-Dinitrophenylhydrazine (DNPH) solution		
2,4-Dinitrophenylhydrazine	Reagent grade, 97%	D199303
Hydrochloric acid	ACS reagent, 37%	320331
2,4-Dinitrophenylhydrazine	Reagent grade, 97%	D199303
Sulfuric acid	ACS reagent, 95.0-98.0%	320501
Ethanol	ACS reagent, ≥99.5% (200 proof), absolute	459844
Dragendorff reagent		
Bismuth(III) nitrate pentahydrate	ACS reagent, ≥98.0%	383074
Acetic acid	ACS reagent, ≥99.7%	320099
Potassium iodide	Puriss. p.a., ACS reagent, ≥99.0%	60400
Vanillin solution		
Vanillin	ReagentPlus®, 99%	V1104
Ethanol	ACS reagent, ≥99.5% (200 proof), absolute	459844
Sulfuric acid	ACS reagent, 95.0-98.0%	320501
Iron(III) chloride solution		
Iron(III) chloride	Reagent grade, 97%	157740
Methanol	Puriss. p.a., ACS reagent, reag. ISO, reag. Ph. Eur., ≥99.8%	32213
Cerium(IV) sulfate solution		
Cerium(IV) sulfate		359009
Sulfuric acid	ACS reagent, 95.0-98.0%	320501
Bromocresol green solution		
Bromocresol green	ACS reagent, dye content 95%	114359
Ethanol	ACS reagent, ≥99.5% (200 proof), absolute	459844
Sodium hydroxide	ACS reagent, ≥97.0%, pellets	221465

Enabling Science to
Improve the Quality of Life

Order/Customer Service (800) 325-3010 • Fax (800) 325-5052
 Technical Service (800) 325-5832 • sigma-aldrich.com/techservice
 Development/Custom Manufacturing Inquiries **SAFC**® (800) 244-1173
 Safety-related Information sigma-aldrich.com/safetycenter

World Headquarters
 3050 Spruce St.
 St. Louis, MO 63103
 (314) 771-5765
sigma-aldrich.com